## Roadkill Monitoring Report I July to 30 September 2022 Tarkine Drive Upgrade

This report details the results of roadkill monitoring activities for the Tarkine Drive over the third three-month period of 2022 and is the thirty-fifth report in total. The Commonwealth Government approved the project to proceed in line with a number of environmental conditions approved under the *Environment Protection and Biodiversity Conservation Act 1999*. Condition 11 of this approval requires that the Department of State Growth publish a roadkill monitoring report every three months, as part of the *Draft Roadkill Monitoring Adaptive Management Plan* (RMAMP), which details the results of monitoring activities.

Tarkine Drive, a 92.7km road, is monitored weekly for signs of roadkill (see Image 1 below). All road upgrade works were completed in December 2014, with the road officially reopened in June 2015.




Image I. Map of project area.

Data collected as part of these monitoring activities is based on pre-defined criteria outlined by the Approval. These criteria are:

- Date and time of identification;
- Location (GPS coordinates);
- Species identified (all species are to be recorded);
- Body condition; and
- Any other notable circumstances.

Monitoring results for this three-month period are detailed in appendices at the end of this report. Six animals were recorded on the Tarkine Drive during this period (see Table 1 in Appendix A).



## Tarkine Drive - Roadkill Monitoring Report - July to September 2022

Across the project area, roadkill numbers continue to remain well below the trigger thresholds outlined as part of the Approval.

All monitoring activities occur under a regular maintenance regime, specified in the RMAMP.

Roadkill mitigation measures were implemented as part of the construction project to minimise roadkill numbers (See Appendix B). These measures include:

- Reduced speed limits;
- Installation of audible 'rumble' strips at 26 separate locations;
- Installation of virtual fencing to prevent animals entering the road (undertaken by Tasmanian Parks and Wildlife Service)
- Use of light-coloured pavement in the road surface to improve visibility;
- Removal of roadside vegetation to reduce proximity of habitat to road;
- Installation of new table drains to reduce ponding of water at the roadside;
- Improved sight distance;
- Wildlife warning signs; and
- Regular monitoring and removal of roadkill to prevent other scavenger animals being attracted to the road.

All of the above-listed measures have already been implemented and continue to be maintained. It is difficult to specifically appropriate reduced numbers of roadkill to a specific measure or circumstance. It is expected that the implementation of these roadkill mitigation measures has assisted in reducing the incidences of roadkill throughout known roadkill hotspots, however this is subject to significant variability in road use, road user behaviours and other chance factors.

Following the approval of the RMAMP, should total numbers of roadkill be found to be increasing, additional mitigation measures will be implemented at pre-existing or newly identified roadkill hotspot locations.



Appendix A: Tables of Results



**Table 1 Q3 Tarkine Upgrade Roadkill Monitoring Results** 

Date	Time	Common Name	<b>Body Condition</b>	Eastings	Northings	<b>GPS Error</b>	Impact Type	Other Circumstances
06/07/2022	10:00							No roadkill identified
13/07/2022	10:00							No roadkill identified
26/07/2022	11:21	Pademelon	5	305720	5445874		vehicle	
02/08/2022	15:06	Wallaby – Bennetts	4	305751	5445631		vehicle	
09/08/2022	10:00							No roadkill identified
19/08/2022	10:00							No roadkill identified
24/08/2022	10:00							No roadkill identified
31/08/2022	10:00							No roadkill identified
2/09/2022	10:00							No roadkill identified
07/09/2022	10:00							No roadkill identified
14/09/2022	13.10	Wallaby – Bennetts	4	305623	5447310		vehicle	
21/09/2022	10:00							No roadkill identified
28/09/2022	14.01	Wallaby – Bennetts		319817	5437342		vehicle	
28/09/2022	14.14	Wallaby – Bennetts		315832	5437028		vehicle	
30/09/2022	13.23	Wallaby – Bennetts		321156	5438082		vehicle	

Appendix B: Map of Installed Mitigation Measures

