Special Information Bulletin 02/-2019 SPPV/LPPV Inspection Reports February 2019

Vehicle Examiners



Introduction;

This bulletin is to provide all Vehicle Examiners information in relation SPPV/LPPV Inspection Reports.

Background;

The current AIS procedures manual requires Type 2/3 vehicle examiners to complete the operator address fields when completing SPV & LPV inspection reports. The new Accreditation Certificates do not show the Accredited Operators Address.

What's Changed;

It is no longer a requirement to complete the address details on the SPPV & LPPV inspection reports. The AIS procedure manual will be amended to reflect the changes. When stocks of these books are required to be re-printed the address section will be removed.

When will this change take effect?

Immediately. The new books will be in circulation when the existing stocks are exhausted.

Questions?

Any further questions regarding this Special Information Bulletin should be directed to AIS Compliance on 6166 3270/3271 or ais@stategrowth.tas.gov.au.

