Special Information Bulletin 03-2017 Takata SRS Airbag Recall September 2017

AIS









Introduction:

This SIB has been developed to provide vehicle examiners, certifiers and proprietors with information regarding vehicles that are subject to a recall in relation to Takata airbags.

Background;

A number of recalls have been announced in Australia for motor vehicles containing Takata airbags. These recalls affect a large number of car makes and models and a small number of motorcycles and trucks.

There have been serious injuries and deaths from vehicles with faulty Takata airbags. The inflator components in Takata airbags may deteriorate and subsequently misdeploy in an incident, with the result of metal fragments from the inflator housing propelling out of the airbag, causing injury or death to the drivers/riders and/or passengers.

All makes and models that are currently affected by the Takata recalls can be found on the link below. A summary of the affected vehicles is also contained in the following pages of this bulletin. Consumers are strongly urged to check whether their vehicles are included in the recall by checking the list, or contacting the dealership or the vehicle manufacturer.

Actions:

If examiners become aware of an affected vehicle that is part of this recall, we request that they advise the owner to contact their local vehicle dealer if they have not already had the airbag assembly replaced. Failure to have the recall actioned is not a reason for rejection.

For up to date website recall information relating to this issue, refer to; https://www.productsafety.gov.au/news/takata-airbag-recalls-affecting-australian-consumers

Questions?

More information and frequently asked questions can be found at the following link; https://www.productsafety.gov.au/news/faqs-on-takata-airbag-recalls



Make & model	Year Range
BMW 5 Series E39, 3 Series E46, X5 E53	2002-2005
Chrysler 300C	2005-2010
Dodge RAM	2004-2010
Ferrari 458, California, FF	2008-2011
Ford Mustang	2006-2014
Honda Civic, CR-V, Jazz	2001-2003
Honda Accord Euro, CR-V, Civic, Jazz	2002-2011
Honda City, CR-V, Insight, Jazz	2006-2014
Honda Accord Euro, City, CR-V, Jazz, Insight	2007-2011
Honda Legend, Odyssey, Accord, MDX	2001-2011
Honda Civic, Accord	2001-2011
Jeep Wrangler JK	2007-2012
Lexus SC430	2000-2003
Lexus IS 250, IS 350, IS 250C, IS-F, LFA	2015-2012
Mazda 2, B Series, BT-50	2006-2011
Mazda 2, RX-8	2003-2014
Mazda 6, RX-8	2002-2014
Mazda 6, RX-8, B2500 ute/cab chassis, B2600 ute/cab chassis, BT-	2002-2011
Mitsubishi GA & GB i-MiEV	2010-2011
Mitsubishi Lancer	2003-2008
Mitsubishi ML & MN Triton	2007-2014
Mitsubishi Pajero NS, NT, NW, NX	2006-2016

Nissan N16 Pulsar, Y61 Patrol, D22 Navara, T30 X-Trail	2001-2004
Nissan N16 Pulsar, D22 Navara, Y61 Patrol, T30 X-Trail, J31 maxima	2004-2008
Nissan D22 Navara, Y61 Patrol	2008-2014
Nissan Tiida	2006-2012
Peformax Silverado, Sierra, Mustang	2007-2008
Subaru Impreza, Forester	2004-2009
Subaru Tribeca, Liberty, Outback	2004-2009
Toyota Corolla, Avensis Verso	2000-2004
Toyota Echo, Rav 4	2002-2003
Toyota Corolla, Yaris, Avensis Verso	2003-2011
Toyota Corolla, Yaris & Rukus	2010-2012
Toyota Echo, Rav 4	2003-2005
MOTORCYCLES American Honda Motor GL1800 Honda GL1800 Goldwing	2012-2015
TRUCKS	
Volvo UD Trucks Quon and Condor	2011-2016